Release Notes
MAGNET Office Solution
March 5, 2024

Table of Contents

Magnet Office V8.1.2 Release Notes
_____

The following revisions have been made to the Magnet v8.0 solution including Office & Magnet Tools.

Please take time to read the release notes. They contain information about the following:

- Issue Resolutions

Information

System Requirements:

Operating System
Microsoft Windows 11 (64-bit version)
Microsoft Windows 10 (64-bit version)
Processor Speed
2GHz Core2 processor or higher
RAM
2GB RAM or more recommended
Memory
Local hard drive space of 2GB or higher recommended
Computer Resolution
1280x1024 display resolution
Internet Connectivity
Can be required by some functionality.

Unless otherwise noted, new features, improvements and resolutions are included in the Magnet Office base configuration. Items that are included in specific modules have a module designation at the end of the description. Module designations:

- **(Survey)** – Survey module
- **(Site Prep)** – Site Prep module

Issue Resolutions

Magnet Office

Resolved MDC/IESDK path issue. This resolves issues with Import/Export of Topcon file formats returning Unable to Start Topcon Utility message.

Resolved issue with Calculate Volume issue reporting that surfaces cannot be the same when using DTMs from a separate project. Calculation now completes using DTM from separate project.

Resolved issue with Road View, not allowing edit of cross section points. Dialog is now displayed allowing for edits. (Site Prep)

Magnet Tools

Resolved MDC/IESDK path issue. This resolves issues with Import/Export of Topcon file formats returning Unable to Start Topcon Utility message.