© 2011-2025 Topcon Positioning Systems, Inc., All rights Reserved

Release Notes

Topcon Office v9.1.1

March 2025

The information contained in this document is confidential and is intended solely for the use of the individual or entity

to which it was sent. You should not copy, disclose or distribute this document without the authority of Topcon Positioning Systems, Inc.

© 2011-2025 Topcon Positioning Systems, Inc., All rights Reserved

Topcon Office V9.1.1 Release Notes

This is a minor version patch release and contains critical fixes only.

Please take time to read the release notes.

Unless otherwise noted, new features, improvements and resolutions are included in the Topcon Office base configuration. Items that are included in specific modules have a module designation at the end of the description. Module designations:

- (Survey) – Survey module
- (Site Prep) – Site Prep module

Information

System Requirements:

Operating System

Microsoft Windows 11 (64-bit version)
Microsoft Windows 10 (64-bit version)

Processor Speed

2GHz Core2 processor or higher

RAM

2GB RAM or more recommended

Memory

Local hard drive space of 2GB or higher recommended

Computer Resolution

1280x1024 display resolution

Internet Connectivity

Can be required by some functionality.

© 2011-2025 Topcon Positioning Systems, Inc., All rights Reserved

Topcon Office V9.1.1 Release Notes 2
Information 2
System Requirements: 2
Notes 4
Fixes 4

© 2011-2025 Topcon Positioning Systems, Inc., All rights Reserved

Notes

This is a patch release

Fixes

- File> Open - fixed issue with job not opening when a Drawing is created with an image in the title block. These jobs can be opened in v9.1.1.
- File> Export DWG - fixed export DWG file if linework was set ByLayer and layer was using Custom linestyle, no file was created.
- Fixed Background images not displaying if "." in filename in some cases
- Modify> Copy - fixed copied linework sometimes being duplicated if the selection also contained text
- Survey> LS Transformation - incorrect results when using 2D when using only 2 point pairs when data in world coordinates
- Takeoff> Takeoff Manager - increased tolerance for overlapping subgrades (Site Prep)
- File> Export KML - fixed some linework such as circles were only exported partially
- File> Import MJF - fixed lines imported with zero thickness set when “Apply office survey code” on.
- File> Export MJF - fixed warning for job with custom projection
- Fixed issue with specific PDF file import crashing