

# marble

*Stylish!*

*Your best choice for  
measuring area and line.*



*Compact, handy, and great look.  
"marble" has made a comeback  
with new plotting feature.*



Metallic Grey



Pastel Blue




Pastel Red

*All plotting can be done  
with one hand.*



### Switching by lines

Point/Stream(continuous) mode key allows conversion between point mode measurement for plotting points on straight lines and stream mode for tracing curves on curved lines.



### Key Operation

#### At P1

Press **PLOT** Key. Move the tracing point to P2.  
You do not need to trace a precise line from P1 to P2.

#### At P2

Press **PLOT** key. Move the tracing point to P3.  
You do not need to trace a precise line from P2 to P3.

#### At P3

Press **POINT/STREAM** key to change to stream mode. Tracing along to curved line to P1. It shows measurement result automatically.

### More Compact and Light Weight

The weight is only 630g and the compact design makes easier measurement.

### More colorful measurement

3 colors, Metallic Grey, Pastel Blue, Pastel Red

### Total and Average as you go

By measuring the same diagram a more number of times, a more accurate average or cumulative measurement for large scale diagrams can easily be carried out with these special keys.

### Measurement of Reduced/Enlarged scale and the vertical scale with different horizontal scale

"marble" can also measure area of a scaled plan. The resulting measurement will be the dimensions of the object measured.

### Auto-close function

Automatically finishes measuring when it is returned to the starting point during measurement.

### Specifications

**Measuring Function** : Area, Line, Side Length(s)

**Measuring Scale** : mm, cm, m, km, in, ft, acre/yd

**Measuring Range** : 300mm × 10m

**Measuring Accuracy** :

± 0.1%(100 × 100mm area measurement)

**Display** : LCD 16 digits on 2 lines

**Minimum Line Reading** : 0.05mm

**Power** : Internal nickel metal hydride battery or AC Charger/Adaptor

**Battery Life** : 20 hours use

**Charging Time** : 15 hours

**Accessories** : Storage Case, AC Charger/Adaptor

**Dimensions** : 250(L) × 110(W) × 40(H)mm

**Weight** : 630g.(without case)

\* Specifications subject to change without notice.

TAMAYA DIGITIZING AREA-LINE METER PLANIX 10S

# marble