

Release Notes MAGNET Field Layout V8.1 January 16, 2024

© 2011-2024 Topcon Positioning Systems, Inc., All rights Reserved

The information contained in this document is confidential and is intended solely for the use of the individual or entity to which it was sent. You should not copy, disclose or distribute this document without the authority of Topcon Positioning Systems, Inc.

MAGNET Field Layout V8.1 Release Notes - Introduction

Please take time to read these Release Notes. They contain information about the following:

New Features Improvements Bug fixes

NOTE:

It is always recommended, before upgrading your field software, user's backup their original job; and following any update to your field software, users perform in-the-field checks to ensure data integrity.

© 2011-2024 Topcon Positioning Systems, Inc., All rights Reserved

Table of Contents

General	Improvement	.s	 	 	4
Resolved	d Issues		 	 	

MAGNET Field V8.1 Release Notes

The following new additions/revisions have been made to Magnet Field V8.1.

Please take time to read the release notes. They contain information about the following:

- New Features
- Feature Enhancements
- Resolved Issues

General Improvements

- Improved the Import and loading time of Autodesk *.dwg and *. dxf files.
- Improved AutoCAD *.dwg import to provide an option to skip hatches when importing a drawing to a job.
- Improved exporting point lists when using the Filter by name option in Exchange>To File> Point List. The export now supports having point name with '-'in the name.
- Added support for the Mini 360 prism.
- Improved Drape Mode. Next Point selection is now available in the Stake Point navigation screen.
- Updated Camera support on the Topcon Fc6000 Field Controller. The default camera is now the back camera.

Resolved Issues

- Addressed an issue in Exchange > To or From File. In MAGNET Field V8, Exchange > Quick Codes > To or From File' would not write the Quick Codes to the file.
- Addressed an issue in Exchange>From Job. When importing From a Job, if the job contained a 3D Model that was transformed, the model returned to its original location.
- Addessed an issue in Edit Points when using the filter by 'Type'. Selecting the External Control Points filter option, after
 applying the filter, no points would show.
- Remove Region and Contour Line references from Layer objects tab.