



---

# GEOPRO FIELD AND OFFICE

---

Version 1.3.3 Release Notes  
August 6, 2018

MARCH 28, 2018

# GeoPro Field V 1.3.3 Release Notes

Please take time to read these Release Notes. They contain information about the following:

- New Features
- Improvements
- Bug Fixes

## **Note:**

It is always recommended before upgrading your field software, users' backup their original job; and following any update to your field software, users should perform in-the-field checks to ensure data integrity.

## [GeoPro Field V 1.3.2:](#)

- GeoPro Field Onboard at times would fail to perform an online activation on the Sokkia DX-i.
- Addressed an issue when the Sokkia GRX1 receiver was configured as the base using GNSS firmware version 3.6 and older and, RTCM 3.0 is selected. The base would not configure correctly.
- Addressed an issue with the virtual port of GRX1 receiver not being set properly.
- Addressed an issue with the position of the measured point not shown in the graphic view when the "Graphic Line" display mode was selected.
- Addressed an issue in robotic TS mode. When exiting the 'Robot' view, automatic measurement would not resume.